
Substance Release Reporting in Idaho






Idaho DEQ Regional Office Numbers

Coeur d'Alene 208-769-1422 Lewiston 208-799-4370 Boise 208-373-0550 Idaho Falls 208-528-2650 Twin Falls 208-736-2190 Pocatello 208-236-6160



^{*}Check the CERCLA hazardous substances (40 CFR 302.4) and EPCRA Extremely Hazardous Substances (40 CFR 355, Appendices A and B) chemical list for reportable quantities

Substance Release Reporting in Oregon






Oregon DEQ Office Numbers

Portland 503-229-5263 Bend 541-388-6146 Pendleton 541-276-4063
The Dalles 541-298-7255 Coos Bay 541-269-2721
Eugene 541-686-7838 Salem 503-378-8240 Medford 541-776-6010



Substance Release Reporting in Washington State





Ecology Regional Office Numbers

Southwest 360-407-6300 **Northwest** 206-594-0000 **Central** 509-575-2490 **Eastern** 509-329-3400

